

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



1/19

(21-001 USA00C








FIG 1





3/19



Step (3)
insert pole
into sleeve

Step (4) - install handle/pin.

Step (1)

Step (2) - remove handle





FIG 2B1



4/1





FIG. 2B2



5/19




FIG. 2B3

6/19





FIG 2C1





FIG. 2C2



7/19




FIG. 2D

9/19





FIG 3A





FIG. 3C









FIG. 3DZ




13/19



14/19








FIG. 7B




FIG. 7A

17/19




FIG. 7D





FIG. 7C



18/19








FIG 8B





2/19